



## **Warning :**

Replacement of the VIBRATION DAMPER

( Item # 3 / BMW Part # 16 12 146 46 28 \* ) may be necessary.

This rubber component is prone to particulation due to aging in gasoline.

It may be cracking, and / or appear to be spongy.

If so, rubber particles will re-contaminate your fuel and be ingested into the new fuel pump.

These rubber particles will damage your fuel pump and void the warranty.

No warranty will be allowed unless proof of the condition of the vibration damper, and / or receipt with concurrent purchase date, is provided.

\* *Euro MotoElectrics does not have this part available; part # **FP-576Damper***